

Work Order (Bid Form)

WORK ORDER INFORMATION

Work Order Name:

Work Order Type: Weatherization

Audit Name: MADISON

CLIENT INFORMATION

Client Name:

Client ID:

Alt. Client ID: 16016SW-0977

AGENCY INFORMATION

Agency: SWHRA

Address: 1574 White AVE

Henderson, TN

Agency Contact: STANFILL, BUTCH

Agency Phone: (731) 989-5111

Fax:

Email Address:

Work Phone: Cell Phone:

Address:

Email Address:

Company Name & Licens	se Number:
Contractor's Signature:	

<u>COMMENT</u>

NOTICE:

All work performed and material must meet all requirements as stated in the Southeast Weatherization Field Guide. It is the contractor's responsibility to pull all necessary permits required for the town or county where the work is being performed. No change order work shall be done until the change order has been approved and signed. If heater is required no air sealing should be done before heater is installed.

731-664-5584

Client Name:

Client ID:

Alt. Client ID: 16016SW-0977

Work Order (Bid Form)

Work Order Name

Report Run On: 5/21/2010

DOE Weatherization Assistant Version 8.5.0

Page 1 of 3

Measures

	Measure 1 Infiltration Redctn			Components					Inspected
C	Comment								
				Makes Mills of File Individual adults and the	Estimated		***************************************	Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Construction Materials/Hardwar e	Seal hole at front door, Hole at water heater, Seal pipes under kitchen sink. Air seal ceiling in furnace closet and add fresh air grill in door, Bath 1 seal pipes under sink	Each	1		Territoria			
2	Labor	Labor	Hour						
3	Construction Materials/Hardwar e	Seall pipes under bath2 sink Hatch cover and trim	Each	1					
4	Labor	Labor	Hour						and the second s
5	Construction Materials/Hardwar e	Weather-strip D1 and D2 add threshold to D2	Each	1					
6	Labor	Labor	Hour						
2	Other Detail			[[
L								A CONTRACTOR OF THE CONTRACTOR	
				Measure Sub Total:			Sub Total:		
	Field Notes:								

Work Order (Bid Form)

	Measure 2 DWH	Pipe Insulation			Componen	ts			Inspected
					Estimated		Actual		
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Insulation	DHW Pipe Insulation	Each	1					
2	Labor	Labor	Each	1			74		
(Other Detail						, ,		
L									
								2.1.7-1-1	
				Measur	e Sub Total:]	Sub Total:	
	Measure 3 CO N	Monitor is Needed			Componen				Inspected
ш	88-4	Description / Comment	Units	04.	Estimated Unit Cost	Total	O++	Actual Unit Cost	Total
	Material / Labor Health and Safety Items	Description / Comment CO monitor	Each	<i>Qty</i> 1		I OLAI	Qty		iotai
2	Labor	Labor	Hour	1					
	Other Detail								
L] []] []		
L				Measur	e Sub Total:			Sub Total:	
	Field Notes:						J		
			Work Or	der Gra	nd Total:		Gran	d Total:	

Client Name: Client ID. Alt. Client ID: 16016SW-0977

Work Order Name: Report Run On: 5/21/2010